L Number	Hits	S arch Text	DB	Time stamp
26	1000	(leadframe r lead-frame or (l ad near	USPAT;	2004/06/13
20	1000	fram)) and ((d f rmabl r b ndable r	US-PGPUB;	21:55
		flexibl) near5 (bar or lead r ti bar r	EPO; JPO;	21.00
		tie-bar r (tie n ar bar)))	DERWENT;	
		tie-par r (tie ii ai parjj)	IBM_TDB	
27	90	(leadfrome or lead frome or (lead near	_	2004/06/13
27	89	(leadframe or lead-frame or (lead near	USPAT;	
		frame)) and ((deformable or bendable or	US-PGPUB;	21:55
		flexible) near5 (bar or lead or tiebar or	EPO; JPO;	
		tie-bar or (tie near bar))) and (hole near2	DERWENT;	
		(position or positioning or location))	IBM_TDB	
28	19	(leadframe or lead-frame or (lead near	USPAT;	2004/06/13
		frame)) and ((deformable or bendable or	US-PGPUB;	21:55
		flexible) near5 (bar or lead or tiebar or	EPO; JPO;	
		tie-bar or (tie near bar))).ti,ab,clm. and (hole	DERWENT;	
		near2 (position or positioning or location))	IBM_TDB	
29	12	(leadframe or lead-frame or (lead near	USPAT;	2004/06/13
		frame)).ti,ab,clm. and ((deformable or	US-PGPUB;	21:56
		bendable or flexible) near5 (bar or lead or	EPO; JPO;	
		tiebar or tie-bar or (tie near bar))).ti,ab,clm.	DERWENT;	
		and (hole near2 (position or positioning or	IBM_TDB	
		location))		
30	9	(leadframe or lead-frame or (lead near	USPAT;	2004/06/13
		frame)).ti,ab,clm. and ((deformable or	US-PGPUB;	21:59
		bendable or flexible) near5 (bar or lead or	EPO; JPO;	
		tiebar or tie-bar or (tie near bar))).ti,ab,clm.	DERWENT;	
		and (hole near2 (position or positioning or	IBM_TDB	
		location)).ti,ab,clm.		
31	6024	(leadframe or lead-frame or (lead near	USPAT;	2004/06/13
		frame)).clm.	US-PGPUB;	22:00
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
32	288	(leadframe or lead-frame or (lead near	USPAT;	2004/06/13
32	200	frame)).clm. and (tiebar or tie-bar or (tie	US-PGPUB;	22:00
		near bar)).cim.	•	22:00
		near varjj.ciii.	EPO; JPO;	
			DERWENT;	
33	4	(leadfrome or load frome or the trans	IBM_TDB	0004/00/40
33	4	(leadframe or lead-frame or (lead near	USPAT;	2004/06/13
		frame)).clm. and (tiebar or tie-bar or (tie	US-PGPUB;	22:01
		near bar)).clm. and (positioning near	EPO; JPO;	
		hole).clm.	DERWENT;	
			IBM_TDB	
34	1	(leadframe or lead-frame or (lead near	USPAT;	2004/06/13
	i	frame)).clm. and (tiebar or tie-bar or (tie	US-PGPUB;	22:01
		near bar)).clm. and (positioning near	EPO; JPO;	
		h i). lm. and deformable. lm.	DERWENT;	
			IBM_TDB	

	2004/06/13
frame)).clm. and (tiebar r tie-bar or (ti US-P PUB;	22:01
near bar)). Im. and (frame near5 hole).clm. EPO; JPO;	
and def rmable.cim. DERWENT;	
IBM_TDB	
36 288 (leadframe or l ad-frame r (l ad near USPAT;	2004/06/13
frame)).clm. and (tiebar or tie-bar or (tie US-PGPUB;	22:01
near bar)).clm. EPO; JPO;	
DERWENT;	*:
IBM_TDB	
	2004/06/13
	22:01
near bar)).clm. and deformable.clm. EPO; JPO;	
DERWENT;	
IBM_TDB	
	2004/06/13
	22:02
near bar)).clm. and deformable EPO; JPO;	22.02
DERWENT:	
IBM_TDB	
	2004/06/13
, constitution of the same of	22:03
near bar)).clm. and (deformable or flexible EPO; JPO;	22.03
or bendable).clm.	
IBM_TDB	
1 - 1	2004/06/13
	22:04
near bar)).clm. and (deformable or flexible EPO; JPO;	
or bendable).clm. and hole.clm. DERWENT;	
IBM_TDB	
	2004/06/13
	22:04
(tie near bar)).clm. and (deformable or EPO; JPO;	
flexible or bendable).clm. and hole.clm. DERWENT;	
IBM_TDB	
l	2004/06/13
	22:04
(tie near bar)).ti,ab,clm. and (deformable or EPO; JPO;	
flexible or bendable).clm. and hole.clm. DERWENT;	·
IBM_TDB	
i	2004/06/13
	22:04
(tie near bar)).ti,ab,clm. and (deformable or EPO; JPO;	
flexible or bendable).ti,ab,clm. and DERWENT;	
hole.clm. IBM_TDB	
	2004/06/13
	22:04
(tie near bar)).ti,ab,clm. and (def rmabl r EPO; JPO;	
fl xibl or b ndabl).ti,ab,clm. and DERWENT;	
h I .ti,ab,clm. IBM_TDB	